

Oil Field Environmental Incident Summary

Incident: 20140706233212 **Date/Time of Notice:** 07/06/2014 23:32

Responsible Party: Missouri Basin Well Service Inc

Well Operator: MBI OIL & GAS, LLC

Well Name: JELLESED SWD 1

Field Name: BLUE BUTTES

Well File #: 1167

Date Incident: 7/6/2014 **Time Incident:** 06:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 95

Sec: 6

Qtr: SE SE

Location Description:

Submitted By: Joshua Staggs

Received By:

Contact Person: Dave Wanner
PO BOX 7
BELFIELD, ND 58622-0007

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	300	Barrels	300	Barrels	300	barrels
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 11/25/2015 **Clean Up Concluded:** 7/7/2014

Risk Evaluation:

Soil and gravel within the Jellesed Primary and Secondary Berm containment.

Areal Extent:

Potential Environmental Impacts:

None at this time.

Action Taken or Planned:

Give proper support to all pipe fixtures in the Jellested. Fix the fitting to the stronger.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/7/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.